General Environmental Incident Summary

Incident: 1948 Date/Time Notice: 6/18/2013 DEM Incident No:

Responsible Party: Lyle Lueck

Date Incident: 6/11/2013 Time Incident: Duration: 1 hours

County: Williams Twp: 154 Rng: 102 Sec: 24 Qtr: SW SE

Lat: 48.14735 Long: -103.74430 Method: Derived from TRS

Location Description: 14103 Hwy 2 West

Submitted By: Lyle Lueck Affiliation:

Address:

City: State: Zip:

Received By:
Contact Person:

14103 Hwy 2 West Williston, ND

Distance Nearest Occupied Building:

Type of Incident: shipping accident

Description of Released Contaminant: Bromoxynil

Volume Spilled: 120.00 gallons Ag Related: Yes

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Container was dropped off forklift while unloading a tractor-trailer. Contents of container were lost into concrete dike.

Risk Evaluation:

None

of Fatalities: 0 # of Injuries: 0 Affected Medium: 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

Chemical was recovered from dike. Small amount of soil in dike was collected and spread out over areas previously treated. Incident was reported to NRC on day of occurrence.

Wastes Disposal Location: In previously treated areas.

Agencies Involved:

Updates

Date: 6/18/2013 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Volume:

Notes:

Assigned to Adam Miller.

Date: 6/19/2013 Status: Inspection Author: Miller, Adam

Updated Volume:

Notes:

Chemical was spilled into a concrete loading pit so nothing escaped the site. The chemical and small amount of water was sucked up with a sump pump and recovered into (2) 250 gallon tanks. Chemical will be used in later pesticide applications. The pit was pressure washed and that solution was collected as well. It will either be field applied to previously treated areas or disposed of as hazmat. All future collections of water will be tested before disposal (this is standard practice for the business).